

MATERIAL SAFETY DATA SHEET

TILE LAB GLOSS SEALER AND FINISH

HMIS

| | |
|---------------------|---|
| HEALTH | 1 |
| FLAMMABILITY | 0 |
| REACTIVITY | 0 |
| PERSONAL PROTECTION | E |

1. Product And Company Identification

Supplier

CUSTOM BUILDING PRODUCTS
10400 Pioneer Blvd., Unit #3
Santa Fe Springs, CA 90670 UNITED STATES

Company Contact: GEORGE MARCINA
Telephone Number: (562) 968-2980 Ext 103
FAX Number: (562) 903-2697
E-Mail: georgem@cbpmail.net
Web Site: www.custombuildingproducts.com

Manufacturer

CUSTOM BUILDING PRODUCTS
10400 Pioneer Blvd., Unit #3
Santa Fe Springs, CA 90670 UNITED STATES

Company Contact: GEORGE MARCINA
Telephone Number: (562) 968-2980 Ext 103
FAX Number: (562) 903-2697
E-Mail: georgem@cbpmail.net
Web Site: www.custombuildingproducts.com

Supplier Emergency Contacts & Phone Number

GEORGE MARCINA: (562) 968-2980

Manufacturer Emergency Contacts & Phone Number

GEORGE MARCINA: (562) 968-2980

Issue Date: 03/20/2006

Product Name: TILE LAB GLOSS SEALER AND FINISH

CAS Number: Not Established

Chemical Formula: Mixture

MSDS Number: 396

Product Code: 3026

2. Composition/Information On Ingredients

| Ingredient Name | CAS Number | Percent Of Total Weight |
|-----------------|-------------|-------------------------|
| 2-BUTOXYETHANOL | 111-76-2 | 1 - 5 |
| ACRYLIC POLYMER | Proprietary | 45 - 55 |

3. Hazards Identification

Primary Routes(s) Of Entry

Inhalation
Skin Contact
Eye Contact
Ingestion

Eye Hazards

Can cause eye irritation.

Skin Hazards

May cause skin irritation.

Ingestion Hazards

Ingestion maybe harmful. Seek medical attention.

MATERIAL SAFETY DATA SHEET

TILE LAB GLOSS SEALER AND FINISH

3. Hazards Identification - Continued

Inhalation Hazards

Inhalation maybe harmful. May cause nose, throat, and lung irritation, headache and nausea.

Subchronic (Target Organ Effects)

Acute lethal exposure to a component of this product, glycol monobutyl ether, resulted in animal studies in congestion of organs including kidney, spleen and lung. Overexposure in animal studies has been suggested as a cause of mild, reversible liver and kidney effects and blood abnormalities.

Chronic/Carcinogenicity Effects

Component of this product, glycol monobutyl ether, although not listed on NTP or IARC, has been shown to cause cancer in laboratory animals.

Reproductive Effects

Component of this product, glycol monobutyl ether, has been shown to cause harm to fetus in laboratory animal studies. Harm to fetus occurred only at levels that harm the pregnant animal.

4. First Aid Measures

Eye

In case of contact, hold eyelids apart and immediately flush eyes with plenty of water for at least 15 minutes. Remove individual to fresh air. Get medical attention immediately if irritation develops and persists.

Skin

In case of contact, immediately flush skin with plenty of water and wash with soap. Remove contaminated clothing. Get medical attention immediately if irritation (redness, rash, blistering) develops and persists.

Ingestion

If the victim is unconscious or drowsy do not give anything by mouth. Get medical or poison center for advice on whether to induce vomiting.

Inhalation

If inhaled, remove to fresh air. Consult a physician immediately if irritation persists. Do not give an unconscious person anything to drink.

Note To Physician

Preexisting disorders of lung (asthma like conditions) liver and kidney may be aggravated by exposure to a component of this product.

5. Fire Fighting Measures

Flash Point: N/A °F

Flash Point Method: N/A

Lower Explosive Limit: N/A

Upper Explosive Limit: N/A

Fire And Explosion Hazards

Material will not burn until dry.

Extinguishing Media

Foam, dry chemical, carbon dioxide, water.

Fire Fighting Instructions

Wear self contained breathing apparatus and protective suit.

6. Accidental Release Measures

Contain spill with inert material such as sand or earth. Transfer to suitable containers for disposal.

MATERIAL SAFETY DATA SHEET

TILE LAB GLOSS SEALER AND FINISH

7. Handling And Storage

Handling And Storage Precautions

Use only with adequate ventilation.

Handling Precautions

Avoid contact with skin and clothing. Avoid contact with eyes. Wash contaminated clothing before re-use.

Storage Precautions

Keep in cool and dry area.

Work/Hygienic Practices

Use good personal hygiene.

Wash thoroughly with soap and water after handling.

8. Exposure Controls/Personal Protection

Engineering Controls

Use with adequate ventilation.

Eye/Face Protection

Safety glasses with side shields or goggles recommended.

Skin Protection

If hands or feet will be exposed, wear impervious gloves and/or boots.

Respiratory Protection

In case of inadequate ventilation and when exposed to dust above the recommended limits, wear a suitable NIOSH-approved respirator.

Ingredient(s) - Exposure Limits

2-BUTOXYETHANOL

ACGIH TLV-TWA 20 ppm

OSHA PEL-TWA 50 ppm (Skin)

OSHA VPEL-- TWA 25 ppm (skin)

9. Physical And Chemical Properties

Appearance

White liquid

Odor

May have very slight ammonia odor.

Chemical Type: Mixture

Physical State: Liquid

Boiling Point: 210 °F 100 °C

Specific Gravity: 1.1

Percent Volatiles: 75

Percent VOCs: 74g/l

Vapor Pressure: Same as water

Vapor Density: N/A

pH Factor: 8-9

Solubility: Dilutable

Viscosity: Water like

Evaporation Rate: N/A

10. Stability And Reactivity

Stability: STABLE

Hazardous Polymerization: WILL NOT OCCUR.

MATERIAL SAFETY DATA SHEET

TILE LAB GLOSS SEALER AND FINISH

| |
|--|
| 10. Stability And Reactivity - Continued |
| Conditions To Avoid (Stability) Avoid heat. |
| Incompatible Materials Strong oxidizing agents. |
| 11. Toxicological Information |
| Ingredient(s) - Toxicological Data ACRYLIC POLYMER ACUTE ORAL TOXICITY LD50=5,000 mg/kg (rat) ACUTE DERMAL TOXICITY LD50 = 5,000 mg/kg (rabbit) |
| 12. Ecological Information |
| No Data Available... |
| 13. Disposal Considerations |
| Dispose in accordance with applicable federal, state and local government regulations. |
| RCRA Information Not considered RCRA Hazardous Waste. |
| 14. Transport Information |
| DOT Shipping Label NOT REGULATED |
| 15. Regulatory Information |
| SARA Hazard Classes Chronic Health Hazard |
| SARA Section 313 Notification This product contains ethylene glycol monobutyl ether, subject to the reporting requirements of Section 313 of the Emergency Planning and Community Right-To-Know Act of 1986 and of 40 CFR 372. |
| Ingredient(s) - U.S. Regulatory Information 2-BUTOXYETHANOL SARA Title III - Section 313 Form "R"/TRI Reportable Chemical SARA - Acute Health Hazard SARA - Chronic Health Hazard SARA - Fire Hazard |
| Ingredient(s) - State Regulations 2-BUTOXYETHANOL New Jersey - Workplace Hazard New Jersey - Environmental Hazard Pennsylvania - Workplace Hazard Massachusetts - Hazardous Substance New York City - Hazardous Substance |
| 16. Other Information |
| HMIS Rating Health: 1 Fire: 0 Reactivity: 0 Personal Protection: E |

MATERIAL SAFETY DATA SHEET

TILE LAB GLOSS SEALER AND FINISH

16. Other Information - Continued

HMIS Rating - Continued

Revision/Preparer Information

MSDS Preparer: GEORGE MARCINA

MSDS Preparer Phone Number: (323) 582-0846

This MSDS Supersedes A Previous MSDS Dated: 05/06/2005

Disclaimer

Although reasonable care has been taken in the preparation of this document, we extend no warranties and make no representations as to the accuracy or completeness of the information contained therein, and assume no responsibility regarding the suitability of this information for the user's intended purposes or for the consequences of its use. Each individual should make a determination as to the suitability of the information for their particular purposes(s).

CUSTOM BUILDING PRODUCTS

Printed Using MSDS Generator™ 2000